Feilo Sylvania International Group Kft. July 2021

| | Good, the transformer can drive the LED lamp well, and output of the LED lamp is more than 90%. | | | | | | | | | |
|-----|---|--|--|--|--|--|--|--|--|--|
| | There is flicker, the transformer can not drive the LED lamp. | | | | | | | | | |
| | There is no flicker, but output of the LED lamp is less than 90%. | | | | | | | | | |
| 2,3 | Minimum 2 or 3 lamps needed connected to 1 transformer | | | | | | | | | |
| | Not tested | | | | | | | | | |

Remarks: The tests were conducted on 15 different transformer in the Lab. The results may vary from one transformer to other transformer.

| S.No | Brand | Model | RefLED Retro MR11 184LM | RefLED Retro MR11 345LM | RefLED Superia Retro V2 MR16 345LM | RefLED Superia Retro V2 MR16 460LM | RefLED Superia Retro V2 MR16 600LM | | RefLED Superia Retro V2 MR16 621LM DIM | ToLEDo G4 300LM | ToLEDo GY6.35 300LM |
|------|---------------|---------------------------|----------------------------|----------------------------|---------------------------------------|---------------------------------------|---------------------------------------|--|---|--------------------|------------------------|
| 1 | TRIDONIC.ATCO | VIP ER R 60VA | | | | | | | | | |
| 2 | TRIDONIC | TE-0060 BASIC 101 | | | | | | | | | |
| 3 | ACTEC | MINI105 | | | | | | | | | |
| 4 | ACTEC | ULTRA70 0-70W | | | | | | | | | |
| 5 | SELF | SET105M(35-105VA) | | | | | | | | | |
| 6 | SELF | SET60T-EL(10-60VA) | | | | | | | | | |
| 7 | OSRAM | HALOTRONIC HTM 70/230-240 | | | | | | | | | |
| 8 | NIKO | 320-00101 | | | | | | | | | |
| 9 | NIKO | 320-00104 | | | | | | | | | |
| 10 | SYLVANIA | HIU112600 | | | | | | | | | |
| 11 | EREA | LASO 70D | | | | | | | | | |
| 12 | HEP | TB60B 230 10-60W | | | | | | | | | |
| 13 | ROLCO | MICRO 60 PFS RN1608 | | | | | | | | | |
| 14 | DESIGNLIGHT | D-AC70U 0-70W | | | | | | | | | |
| 15 | PHILIPS | ET-E 60 | | | | | | | | | |