






3032819, 20 EB  
3032825, 26 EB E3  
3032849, 50 DB  
3032855, 56 DB E3  
3032871, 72 DALI  
3032877, 78 DALI E3


3034833, 34 EB MW  
3034937, 38 DB MW  
3032946, 47 EB E1  
3032954, 55 DB E1  
3032962, 63 DALI E1

ta 25°C




**6** ⚡ ! ENSURE DRIVER HAS **NOT** BEEN POWERED FOR AT LEAST 1(ONE) MINUTE **BEFORE** CONNECTING LED STRING.


3032919, 20 EB




3032849, 50 DB  
3032871, 72 DALI




3032946, 47 E1  
3032825, 26 E3




3032954, 55 DB E1  
3032855, 56 DB E3



3034833, 34 EB MW



3034937, 38 DB MW



**7** ⚡ 3032825, 26 EB E3  
3032855, 56 DB E3  
3032877, 78 DALI E3

JAN	FEB	MAR	APR
MAY	JUN	JUL	AUG
SEP	OCT	NOV	DEC
2013	2014	2015	2016
2017	2018	2019	2020
2021	2022	2023	2024

